


LIGHTWAY INDUSTRIES

INSTALLATION INSTRUCTIONS



WARNING – Before starting the installation, disconnect the power by turning off the circuit breaker or removing fuse. Turning the power off using the light switch is not sufficient to prevent electrical shock.

1. For proper installation, have a qualified electrician install this product.
2. Expose the supply wiring from the outlet box.
3. Run the supply wiring out of the outlet box.
4. Attach the canopy mounting bracket to the outlet box using mounting screws (provided by others).
5. Attach the chassis assembly to the tube by threading the tube into the coupling on the chassis.
7. Attach the tube to the canopy bracket by rotating the assembly so that the half ball can be pushed in the mounting bracket by lining up the groove in the half ball with the bracket tabs and rotate the ball in.
8. Make sure that the half ball is secure in the canopy mounting bracket and line up the groove in the half ball with the alignment tab in the mounting bracket cavity so that the half ball can swing slightly but not rotate.
9. Connect the wires:
 - 9.1. Connect the grounding wire (green of bare copper) from the supply circuit to the green wire(s) from the fixture.
 - 9.2. Connect the white wire from the fixture to the white wire(s) of the supply circuit.
 - 9.3. Connect the black wire from the fixture to the black wire(s) of the supply circuit.
10. Secure the canopy to the mounting bracket by lining up the tabs on the bracket and rotate the canopy until secure.
 11. Install the lamps. Do not exceed recommended wattage.
 12. Install the lens.
 13. Restore power.

